



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: October 3, 2006

Supervisor

10271

Mine Name: Red Warrior Limestone
Operator Name: L&M Engineering & Construction
Jerry Lewis
756 North Dixie Drive
P.O. Box 898
St George, Utah 84771

Permit number: S/053/012
Date: September 13, 2006
Time: 8:00 AM

Inspector(s): Doug Jensen

Other Participants: Kay Jean Mathews, Mark Mathews, Mark Fonger--Red Warrior Limestone

Mine Status: Inactive

Weather: Clear, Warm

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Discuss future mining plans with the new operator.

1. Permits, Revisions, Transfer, Bonds

Red Warrior Limestone recently applied to take over the operation and reclamation liability for this site.

Directions to Site:

See previous inspection report.

Inspection Summary:

The meeting was to discuss possible plans for the operation and expansion of the site. The site presently has more than 4 acres disturbed. While any operation could operate within this area for a while, but if mining progresses very much the operator should consider applying for a large mine permit.

Portions of the road has been washed out due to recent storms, before any mining can commence, the road will need to be repaired. There was a fire in this area this spring therefore much of the area around the permit area has been impacted. The fire did not burn down into the operation but burned the areas around the site.


Red Warrior mentioned that they were considering putting a stockpile below the site near Highway 91. I informed them that that property was probably owned by the BLM and they would need to discuss this plan with the St. George field office.

The site was GPS'd and photographed previously so I did not collect any addition data in these areas.

Conclusions and Recommendations:

I will continue to work with the operator in order for them to achieve a greater understanding of the permitting process.

Inspector's Signature



Date:

9/27/06

dj:pb
cc:

Red Warrior Limestone
John Blake, ML-44686